

Amy Ow

From: Jessica Henderson-McBean <JHenderson-McBean@swca.com>
Sent: Thursday, January 7, 2021 5:29 PM
To: Camille Leung
Cc: Kristen Outten; Amy Ow
Subject: Highland Estates Inspection Report - 1/7/2020
Attachments: Lot 9_10 Boxes.JPG; Lot 11 Silt Fence.JPG; Lot 11 Windbreak.JPG; Inspection_Report_Form_1.7.21.pdf

CAUTION: This email originated from outside of San Mateo County. Unless you recognize the sender's email address and know the content is safe, do not click links, open attachments or reply.

Hi Camille,

I conducted my site inspection at Highland Estates today. Bob had not addressed my action items from yesterday but he assured me that he had laborers coming to the site tomorrow to help him address these issues. Please find attached my report from today's inspection.

Thanks!

Jessie Henderson-McBean
Project Manager / Biologist

SWCA Environmental Consultants
60 Stone Pine Road, Suite 100
Half Moon Bay, CA 94019
P 650.440.4160 x 6410 | C 805.712.8794



Visit Our New [Website!](#)

The contents of this email and any associated emails, information, and attachments are CONFIDENTIAL. Use or disclosure without sender's authorization is prohibited. If you are not an authorized recipient, please notify the sender and then immediately delete the email and any attachments.

From: Jessica Henderson-McBean
Sent: Thursday, January 7, 2021 5:17 PM
To: robertpellegrine@yahoo.com
Cc: 'Bob Pellegrine' <Bob.P@nexgenbuilders.com>; cleung@smcgov.org; 'Noel Chamberlain' <noel@nexgenbuilders.com>; Kristen Outten <koutten@swca.com>; 'Amy Ow' <aow@smcgov.org>
Subject: Highland Estates Site Visit - 1/7/2020

Hi Bob,

It was nice to see you onsite today. As we discussed, please address the following action items prior to my next inspection (Wednesday 1/13/2021)

Lots 9/10

- Please retrieve the boxes that have blown downslope, and out of the work area on the East side of the project.

Lot 11

- Please repair the silt fence on the south side of the work area, where the lumber pile is sitting on top of a portion of the silt fence.
- Please repair the windbreak fence, which had become detached from one of the poles and was falling down.

Feel free to give me a call if you would like to discuss.

Thanks so much,

Jessie Henderson-McBean

Project Manager / Biologist

SWCA Environmental Consultants

60 Stone Pine Road, Suite 100

Half Moon Bay, CA 94019

P 650.440.4160 x 6410 | C 805.712.8794



Visit Our New [Website!](#)

The contents of this email and any associated emails, information, and attachments are CONFIDENTIAL. Use or disclosure without sender's authorization is prohibited. If you are not an authorized recipient, please notify the sender and then immediately delete the email and any attachments.